


## **Firmware Release Note**



The version (s) indicated here above has (have) been tested and validated by the Technical Support Department.

## **Technical Notes**

## Version 4.20

- Evolution : add preset layouts
- Evolution: [STE200] Payload ID management for SDI outputs
- Correction: The "format" menu of output 2 shouldn't appear for Smart-Edge products
- Correction: [STE200] Problem of frame capture size when switching capture source from RCS
- Correction: The "rate" menu of output 2 shouldn't appear for Smart-Edge products
- Correction: Automatic exit of menu "Motion correction" doesn't work when switching to a non-interlaced input
- Correction: [STE100] Some status summary menu don't have the same duration
- Correction: [STE200] The logo Chroma-key grabber position doesn't change on output 2
- Correction: When changing the HV size of a PIP, the H size suddenly goes to 0
- Correction: Strobbing effect for sources whose rate is really close to the output rate
- Correction: [STE200] The tolerance setting of logo capture keying doesn't work
- Correction: [STE200] When switching the logo capture source from RCS, the grabber doesn't disappear from the
  previous capture source

 $\begin{array}{cccc} \text{MM:} & \underline{K = FF0C} \\ \text{MF:} & \underline{K = 54F6} \\ \text{CA:} & \underline{V = 0037} \\ \text{FA:} & \underline{V = 0044} \\ \text{TH:} & \underline{V = 0037} \\ \text{CS:} & \underline{V = 0009} \\ \end{array}$ 

Underlined = New Checksum

